



MS Series




DASH NO.	DIM A	DIM B	DIM C	DIM D	DIM E	DIM F
2	.16	.28	.43	.27	.51	.73
3	.16	.32	.53	.37	.61	.73
4	.22	.43	.64	.42	.72	.73
5	.22	.53	.75	.53	.83	.73
6	.22	.64	.86	.64	.94	.73
7	.22	.75	.97	.75	1.05	.73
8	.22	.86	1.08	.86	1.16	.73


PD4



PD2



MSA/MSB Series



DASH NO.	DIM A	DIM B	DIM C	DIM D
2	.430	.215	.120	.350
3	.530	.320	.265	.450
4	.640	.430	.320	.560
5	.750	.540	.375	.670
6	.860	.650	.430	.780